

Artek General Laborer

Job Description: Hopper Filling

- Employee is to use 5 gallon buckets to fill hoppers with resin. Resin used is determined by matching label on hopper with the label on the Gaylord. This operation is performed every 1.5 – 2 hours throughout shift.

Job Description: Line Operator

Line operator must be capable of maintaining 54 extrusion lines. Maintaining lines includes the following:

- Measure and cut all extrusion lines to the lengths indicated on the hoppers.
- Stack material neatly on the appropriate skids
- Bundle material as required.
- Inform Lead-person of any imperfections or adjustments needed.
- Line operator is required to sweep lines at the end of shift.

Job Description: General fabrication

- Follow all safety rules that apply to the equipment being used.
- Never operate equipment without proper training
- Before cutting any material, double check measurement
- Package material neatly
- Clean up area used before shift ends.

*All the above job descriptions include on-the-job training.

*Most commonly used tools include tape measure and circular saws.